

Multilin 469 Motor Protection System

Energvista SW Revision 5.25 Release

GE Publication Number: GER-4720

Copyright © 2015 GE Digital Energy

Overview

Summary

GE Digital Energy issues the Multilin SR 469 Energvista setup SW 5.25 release. Highlights of this release include:

- PDF water mark issue fixed
- Release Date: **November 20, 2015**

Upgrading from a previous version of the 469 Setup SW to the new 5.25 can be done via Energvista Launchpad or downloaded directly at:

<http://www.gedigitalenergy.com/app/ViewFiles.aspx?prod=469&type=7>

Release details

In the following change descriptions, a revision category letter is placed to the left of the description. Refer to the Appendix at the end of this document for additional details.

Enervista setup SW 5.25

E Minor Bug fixes

Enervista Setup SW V5.25 takes care of the following.

- PDF water mark issue has been resolved in Settings file and Compare settings file PDF reports.
- Silent installation support has been added

Please contact your local Multilin sales representative or Multilin Customer Service Department (CST) for any questions regarding this upgrade.

Appendix

Change categories

This document uses the following categories to classify the changes.

Table 1: Revision categories

Code	Category	Comments
N	New feature	A separate feature added to the relay. Changes to existing features even if they significantly expand the functionality are not in this category
G	Change	A neutral change that does not bring any new value and is not correcting any known problem
E	Enhancement	Modification of an existing feature bringing extra value to the application
D	Changed, incomplete or false faceplate indications	Changes to, or problems with text messages, LEDs and user pushbuttons
R	Changed, incomplete or false relay records	Changes to, or problems with relay records (oscillography, demand, fault reports, etc.)
C	Protocols and communications	Changes to, or problems with protocols or communication features
M	Metering	Metering out of specification or other metering problems
P	Protection out of specification	Protection operates correctly but does not meet published specifications (example: delayed trip)
U	Unavailability of protection	Protection not available in a self-demonstrating way so that corrective actions could be taken immediately
H	Hidden failure to trip	Protection may not operate when it should
F	False trip	Protection may operate when it should not
B	Unexpected restart	Relay restarts unexpectedly

The revision category letter is placed to the left of the change description.

Multilin technical support

GE Digital Energy - Multilin contact information and call center for product support is shown below:

GE Digital Energy - Multilin
 650 Markland Street
 Markham, Ontario L6C0M1
 Canada

Telephone: 1- 905-927-7070 or 1-800-547-8629 (North America), +34 94 485 88 00 (Europe)
 Fax: 905-927-5098 (North America), +34 94 485 88 45 (Europe)

E-mail: multilin.tech@ge.com
 Home Page: www.GEDigitalEnergy.com/Multilin