GE
Grid Solutions

SR Family

Multilin 750/760 Feeder Protection System

Enervista Software Revision 7.46 Release Notes

Summary

GE Grid Solutions issues the Enervista 750/760 Setup software 7.46 release. Highlights of this release include:

- Group settings file conversion issue resolved.
- Quick connect issue resolved.
- Deleted Offline settings file handling is improved.
- Menu now supports adding existing settings files to offline tree.
- Enervista 750/760 Setup software now supports Windows 7, 8.1 and 10 (English OS)

- Release Date: **23rd March 2018**

Upgrading from a previous version of the Enervista 750/760 Setup software to the new 7.46 version can be done via EnerVista Launchpad or downloaded directly at:

http://www.gedigitalenergy.com/app/ViewFiles.aspx?prod=750&type=7

Release details

In the following change descriptions, a revision category letter is placed to the left of the description. Refer to the Appendix at the end of this document for additional details.

Enervista 750/760 Setup software 7.46

E   **Group settings issue resolved while settings file conversion.**

- When a v7.30 settings file is converted to a v7.40 setting file, Group 1 and Group 2 settings now retain the correct values.

E   **Quick connect issue is resolved.**

- While communicating using Quick Connect, should changes to the cable to other devices occur without refreshing Quick Connect, the Enervista 750/760 Setup software now displays a warning message.

- Quick Connect is now shown in a separate node, to easily identify the Quick Connect device.

E   **Deleted Offline settings file handling is improved.**

- Enervista 750/760 Setup now displays a message when the application is opened and the user deletes any offline settings files (used by application) from the hard disk.

E   **Menu now supports adding existing settings files to offline tree.**

- In the menu under **File > Open** the filter for adding "*.750 | *.760" settings files to the offline tree has been expanded to include waveform files (*.CSV).

Please contact your local Multilin sales representative or Multilin Customer Service Department (CST) for any questions regarding this upgrade.

Appendix

Change categories

This document uses the following categories to classify the changes.

Table 1: Revision Categories

Code	Category	Comments
N	New feature	A separate feature added to the relay. Changes to existing features even if they significantly expand the functionality are not in this category
G	Change	A neutral change that does not bring any new value and is not correcting any known problem
E	Enhancement	Modification of an existing feature bringing extra value to the application
D	Changed, incomplete or false faceplate indications	Changes to, or problems with text messages, LEDs and user pushbuttons
R	Changed, incomplete or false relay records	Changes to, or problems with relay records (oscillography, demand, fault reports, etc.)
C	Protocols and communications	Changes to, or problems with protocols or communication features
M	Metering	Metering out of specification or other metering problems
P	Protection out of specification	Protection operates correctly but does not meet published specifications (example: delayed trip)
U	Unavailability of protection	Protection not available in a self-demonstrating way so that corrective actions could be taken immediately
H	Hidden failure to trip	Protection may not operate when it should
F	False trip	Protection may operate when it should not
B	Unexpected restart	Relay restarts unexpectedly

The revision category letter is placed to the left of the change description.

For further assistance

For product support, contact the information and call center as follows:

    GE Grid Solutions

    650 Markland Street

    Markham, Ontario

    Canada L6C 0M1

    Worldwide telephone: +1 905 927 7070

    Europe/Middle East/Africa telephone: +34 94 485 88 54

    North America toll-free: 1 800 547 8629

    Fax: +1 905 927 5098

    Worldwide e-mail: multilin.tech@ge.com

    Europe e-mail: multilin.tech.euro@ge.com

    Website:http://www.gegridsolutions.com/multilin/